

In an injection-molding machine, the rapid traversing over long distances takes place with the aid of linear drives (L1, L2), the "rotor" (H1, H2) which is a component part of the machine construction.